

**Test Report** No.: CANEC23011891901 Date: Oct 26, 2023 Page 1 of 4

Client Name: CHANGZHOU SUN PLUS LAMINATE CO.,LTD

Client Address: NO.16 WUQING ROAD, WEIXING INDUSTRY, HENGLIN TOWN, CHANGZHOU, CHINA

Sample Name: High pressure laminate

Model No.: HGS

Product Specification: Thickness 1mm

The above sample(s) and information were provided by the client.

SGS Job No.: GZP23-016486 Sample Receiving Date: Oct 18, 2023

Testing Period: Oct 18, 2023 ~ Oct 24, 2023

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

Test Requirement	Conclusion
Asbestos	See Results

Signed for and on behalf of SGS-CSTC Standards Technical Ser

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Jessieli

Jessie-JX Li Approved Signatory



356803B1



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN Doccheck@ass.com.

No.198, Kezhu Road, Science Chy, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技术产<mark>业开发区</mark>科学城科珠路198号 邮编: 510663 t (86–20) 82155555 t (86–20) 82155555 www.sgsgroup.com.cn sgs.china@sgs.com



**Test Report** No.: CANEC23011891901 Date: Oct 26, 2023 Page 2 of 4

## Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description	
SN1	A1	CAN23-0118919-0001.C001	Dark-brown board with light brown/brown surface	

#### Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

### **Asbestos**

Test Requested: According to the requirement of the revision of SOLASS in MSC.282(86) resolution

approve by IMO and "Hong Kong International Convention for the Safe and

Environmentally Sound Recycling of Ships, 2009" and the marine environment protection committee MEPC.269(68) "2015 Guidelines for the Development of the Inventory of

Hazardous Materials", asbestos in the submitted sample as client specified.

Test Method: With reference to NIOSH 9000:2015 and ISO 22262-1:2012, analysis was performed by

XRD/PLM.

Test Item(s)	CAS No.	Unit(s)	MDL	A1
Actinolite	77536-66-4	%	0.1	Negative
Amosite	12172-73-5	%	0.1	Negative
Anthophyllite	77536-67-5	%	0.1	Negative
Chrysotile	12001-29-5 /132207-32-0	%	0.1	Negative
Crocidolite	12001-28-4	%	0.1	Negative
Tremolite	77536-68-6	%	0.1	Negative

#### Notes

(1) Negative = the absence of asbestos, Positive = the presence of asbestos.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com



**Test Report** 


No.: CANEC23011891901

Date: Oct 26, 2023

Page 3 of 4

## **ATTACHMENTS**

# **Asbestos Testing Flow Chart**





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CND poschedomics company.

No.198、Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China. 510663 中国・广东・广州高新技<mark>术产业开</mark>发区科学城科珠路198号 邮编: 510663 t (86–20) 82155555 t (86–20) 82155555 www.sgsgroup.com.cn sgs.china@sgs.com



**Test Report** 


No.: CANEC23011891901

Date: Oct 26, 2023

Page 4 of 4

Sample Photo:





SGS authenticate the photo on original report only

\*\*\* End of Report \*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/en/Terms-and-Conditions">https://www.sgs.com/en/Terms-and-Conditions</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CND poschedomics company.

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663 中国・广东・广州高新技<mark>术产业开</mark>发区科学城科珠路198号 邮编: 510663 t (86–20) 82155555 www.sgsgroup.com.cn t (86–20) 82155555 sgs.china@sgs.com